



PROJECT	SERVICE PROVIDED	LOCATION
Federal Law Enforcement Training Center	Window Assessment & Study	Brunswick, GA
Verdant at the Village Apartments	Structural & Shoring Assessment for Fire-Damaged Building	Beachwood, OH
Saturn Press	Brick Façade Assessment	Bedford, OH
Peck Plaza Condominiums	Post-Hurricane Window & Door Assessment	Daytona Beach, FL
Saalfield Square	Foundation Assessment	Akron, OH
Independence High School	Roof And Masonry Wall Leak Study	Independence, OH.
E-Poch Properties	Structural Assessment of Corroded Roof Steel	Cleveland, OH
Seven Hills Recreation Center	Roof Study Assessment	Seven Hills, OH
Memorial School – Cleveland Municipal School District	Roof And Masonry Wall Leak Study	Cleveland, OH
Weathervane Lane Apartments	Structural & Shoring Assessment for Fire-Damaged Apartment Building	Akron, OH
BFG Federal Credit Union	Assessment of Bowing Foundation Wall	Hudson, OH
Cuyahoga Falls High School	Entrance Canopy Structural Assessment	Cuyahoga Falls, OH
Emerald Performance Materials	Concrete Floor Assessment & Repair Details	Akron, OH
Kids Ahead Daycare	Roof Assessment for Hail Damage	Mogadore, OH
Gateway Elem./Middle School - Conneaut School Dist.	Window & Roof Assessments	Conneaut, OH
David L. Lawrence Convention Ctr.	Metal Soffit Panels Assessment	Pittsburgh, PA
Hamilton Avenue Building	Structural Evaluation For Building Addition	Cleveland, OH
John Hay High School – Cleveland School Dist.	Window Assessment	Cleveland, OH
Alexander Hamilton School – Cleveland Municipal School Dist.	Window Assessment	Cleveland, OH
Emerald Performance Materials	Concrete Slab & Floor Steel Corrosion Assessment & Repair	Akron, OH
Electrolizing Corp. of Ohio	Structural Evaluation of Building Steel	Cleveland, OH
Warehouse Pre-engineered Building	Structural Building Assessment of Hurricane Damage	Pensacola, FL
Hudson & Front	Assessment of Fire-Damaged Roof Joists	Cuyahoga Falls, OH

Detroit Airport	Assessment of Terminal Shuttle Guideway Anchors	Detroit, MI
Tinora High School – Delaware School District	Gymnasium Glulam Beam Evaluation	Defiance, OH
Silver Lake Towers Apartments	Parking Garage Repair Study	Silver Lake, OH
Midtown Towers #2 – apartment complex	Fire-Damaged Floor Joist Evaluation & Repair	Parma, OH
Commercial Pole Barn	Wind Damage Assessment	Navarre, OH
Tides Fall Condominiums	Post-Hurricane Building Wall Evaluation	Ormand Beach, Fl.
Seychelles Condominiums	Post-Hurricane Building Wall Evaluation	Daytona Beach, Fl.
Noveon, Inc.	Plate Thickness Evaluation of Coal Elevator	Akron, OH
NexPak	Roof Joist Evaluation & Repair	Canton, OH
Social Security Office	Shoring Recommendations & Repair Details	Cleveland, OH
Consolidated Label	Wind Damage Assessment to Metal Roof Deck	Lakeland, FL
SunAg Packing House	Hurricane Damage Wall Repair	Fellsmere, FL
Walmart	Roof Joist Assessment	Ravenna, OH
Hunter Manufacturing	Roof Collapse Assessment & Reconstruction	Solon, OH
Noveon, Inc.	Structural Evaluation of Damaged Building	Akron, OH
Residential Site	Retaining Wall Failure Assessment & Repair	Cuyahoga Falls, OH
Village Green Apartments	Structural Evaluation of Fire Damage	Beachwood, OH
Morton Salt	Roof Truss Corrosion Evaluation & Repair	Rittman, OH
Distribution, Inc.	Warehouse Roof Collapse & Repair	Columbus, OH
Rubbermaid	Structural Evaluation of Tornado Damage	Wooster, OH
Factory Fire	Evaluation of Fire Damaged Steel	Akron, OH
Kane Enterprises	Stability Evaluation of Fire-Damaged Masonry Walls	Akron, OH
Heating & Cooling Products, Inc.	Bowstring Truss Failure Cause & Origin Report & Repairs	Mt. Vernon, OH
Residential Pole Barn	Structural Evaluation of Wind Damage	Wadsworth, OH
Residential House Fire	Structural Evaluation of Fire Damage	Euclid, OH.
Eur-Asian Auto Repair	Roof Collapse Shoring Recommendations	Cleveland, OH
Residential Foundation	Evaluation of Cracked Foundation	Akron, OH
Velvet Ice Cream	Structural Evaluation of Fire-Damaged Trusses	Utica, OH
Cross Creek Development	Segmental Wall Evaluation	Cuyahoga Falls, OH
Accuride Inc.	Evaluation of Fire-Damaged Roof Joists	Cuyahoga Falls, OH.
King's Medical	Floor Load Analysis	Hudson, OH
Howard Johnson Motel	Entry Canopy Damage Evaluation	Perrysburg, OH
Jones Excavating	Structural Assessment Of Building Damage	Tallmadge, OH.

More detailed Forensic Project Profiles or Sample Reporting Available Upon Request